TO:	Art Perez
	Honeywell International
	714 Peachtree St NE
	6th Floor
	30308-2179

FROM:	Matt Arnold on behalf of the FIPS 201 Evaluation Program
DATE:	6/8/2022
RE:	Updated approval of Products/Services for Listing on the GSA APL

Office of Management and Budget (OMB) issued M-19-17 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture, and ensures compliance, consistency and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementer.
Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

1 Category-PACS Infrastructure

1.1 APL Certification Number

- **(APL#10063)**
  - o Honeywell Pro-Watch CE Server Software
  - o Mercury LP25000 Intelligent Controller
  - o Mercury LP1502 Intelligent Controller
  - o Mercury MR52S3 Dual Reader Board
  - o Honeywell PW7K1ICE/LP1501 Single Door Controller
  - o Honeywell PW7K1IC/LP1502 Honeywell PW-7000 Intelligent Controller
  - o Honeywell PW7K1R2 Honeywell PW-7000 2 Reader SIO Board
  - o Mercury LP4502 Intelligent Controller
  - o Mercury LP4502 AAM Embedded Authentication Module
  - o Mercury MR62e Single Door POE Reader Board
  - o Mercury MR50S3 Series 3 Single Reader Board

1.2 Product/Service Information

Organization Name:	Honeywell
Name of Product or Service:	Pro-Watch CE Server Software
Part Number:	PW60CESW
Hardware Version:	N/A
Software Version:	6.0
Firmware Version:	N/A

Organization Name:	Mercury
Name of Product or Service:	Intelligent Controller
Part Number:	LP2500
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	1.29.5

Organization Name:	Mercury
Name of Product or Service:	Dual Reader Board
Part Number:	MR52S3
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	3.21.12

Organization Name:	Mercury
Name of Product or Service:	Intelligent Controller
Part Number:	LP1502
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	1.29.5

Organization Name:	Honeywell

Name of Product or Service:	PW7K1ICE/LP1501 Single Door Controller
Part Number:	PW7K1ICE/EP1501
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	1.29.5

Organization Name:	Honeywell
Name of Product or Service:	Honeywell PW-7000 2 Reader SIO Board
Part Number:	PW7K1R2
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	3.21.13

Organization Name:	Honeywell
Name of Product or Service:	Honeywell PW-7000 Intelligent Controller (Honeywell version Mercury LP1502)
Part Number:	PW7K1IC/LP1502
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	1.29.5

Organization Name:	Mercury
Name of Product or Service:	Intelligent Controller
Part Number:	LP4502
Hardware Version:	
Software Version:	
Firmware Version:	1.30.2

Organization Name:	Mercury
Name of Product or Service:	Embedded Authentication Module on LP450
Part Number:	LP4502 AAM
Hardware Version:	
Software Version:	
Firmware Version:	5.20.25

Organization Name:	Mercury
Name of Product or Service:	Single Door POE Reader Board
Part Number:	MR62e
Hardware Version:	
Software Version:	
Firmware Version:	3.21.0

Organization Name:	Mercury
Name of Product or Service:	Series 3 Single Reader Board

Part Number:	MR50
Hardware Version:	
Software Version:	
Firmware Version:	3.21.12

1.

1.3 Document History

Status	Date	Comments
Approved	7/21/2015	Final Approval Date for APL# 10063
Update	8/27/2015	Disclose TAA Compliance Information.
Update	2/19/2019	Updated Approval for Upgrade to Pro-Watch 4.4 and HID pivCLASS 5.7.1
Update	9/29/2021	Update approved for Pro-Watch and HID pivCLass
Update	6/8/2022	Update of Honeywell Software, HID PivCLASS Software, and addition of embedded authentication.

1.4 Restrictions:

Honeywell Pro-Watch (**APL #10063**) has been tested and approved as a component of a fully compliant ICAM Solution. The end to end solution components used to test the ICAM compliance of the approved solution are listed below.

● Validation System   (**APL# 10064**)
- o pivCLASS Registration Engine for Honeywell Pro-Watch
- o pivCLASS Certificate Manager
- o pivCLASS Reader Services
- o pivCLASS IDPublisher
- o pivCLASS Authentication Module

● PIV Reader
- o pivCLASS RP40 Contactless Reader (APL#**10003**)
- o pivCLASS RK40 Contactless Reader + PIN (APL# **10004**)
- o pivCLASS RPK40 Contactless Reader + PIN (APL# **10005**)
- o pivCLASS R40 Contactless Reader (APL# **10006**)
- o pivCLASS RKCL40 Contact/Contactless Reader with PIN (APL# **10007**)
- o pivCLASS RPKCL40 Contact/Contactless Reader with PIN (APL# **10008**)
- o pivCLASS RPKCLB40 Contact/Contactless Reader with PIN & BIO (APL# **10026**)
- o pivCLASS RKCLB40 Contact/Contactless Reader with PIN & BIO (APL# **10052**)
- o Embedded Only
  - ▪ pivCLASS RPK40 Contactless Reader + PIN, HDX OSDP (APL# **10008**)

- ▪ HID Signo contactless smart card reader with keypad (APL #**10134**)
- ▪ HID Signo contactless smart card reader (APL #**10135**)
- ▪ HID Signo contactless smart card reader with keypad, mullion (APL #**10136**)
- ▪ HID Signo contactless smart card reader, mullion (APL #**10137**)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases, and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons including but not limited to:

- ● Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.

- ● Problems discovered in your listed product/service (or class of product/service) are not addressed within time frames specified by the Program.

Refer to applicable Agreements and Program documents for specific details regarding ongoing compliance including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Matthew Arnold
GSA OGP
(703) 254-6750
Matthew.Arnold@gsa.gov